

POWERTEX

GB Instruction for use
DK Brugsanvisning

POWERTEX


Shackle PBSB/PBSP/PDSB/PDSP




User Manual

POWERTEX Shackles

Instruction for use (GB) (Original instructions)




PDSB with safety bolt




PDSP with screw pin

WLL ton	Pin Ø d1	a*	c*	d	d2	H1 PDSB	H1 PDSP	Weight PDSB kg	Weight PDSP kg
mm									
0,33	6 / 6,3	10	21,85	5	14,5	33,5	29	0,027	0,025
0,5	8	13	22	6,5	17,5	42,5	38	0,05	0,042
0,75	9,5	13,5	25,5	8	21	47	42,5	0,086	0,068
1	11,2	17	30,9	10	25	56,5	51,5	0,160	0,130
1,5	12,7	18,5	36,4	11	27	63,5	58	0,215	0,185
2	15,8	20,6	41,4	12,7	30,5	75,5	67	0,340	0,29
3,25	18,8 / 19	27	51	16	40	92	85	0,6	0,58
4,75	22	32	63	19	48	106	98,5	1,02	0,93
6,5	25	37	72	22	54	120	114	1,6	1,45
8,5	28	43,5	81,75	26,5	60	135	129,5	2,3	2,06
9,5	32	48	94	29	68	143	144	3,33	2,91
12	35	53	102	32	76	164	157	4,15	4,15
13,5	38	59	113,5	35	84	182	171	5,87	5,5
17	42	62	123	38	92	195	186	7,6	6,97
25	50	75	148	45	106	224	227	11,7	11,22
35	55	84	174,5	52	122	248	253	17,84	16,36
55	70	107	205,5	66	145	302	318	33	31

*Tolerance: +/- 5%



PBSB with safety bolt



PBSP with screw pin

WLL tons	Pin Ø d1	a*	c*	d	d2	e	H1 PBSB	H1 PBSP	Weight kg
mm									
0,33	6 / 6,3	10	22,6	5	14,5	15,5	33,5	29	0,026
0,5	8	13	29	6,5	17,5	20	42,5	38	0,048
0,75	9,5	13,5	31	8	21	21,5	47	42,5	0,082
1	11,2	17	36,5	10	25	26,2	56,5	51,5	0,150
1,5	12,7	18,5	42,9	11,3	27	29,5	63,5	58	0,20
2	15,8	20,6	47,75	12,7	30,5	33,3	75,5	67	0,30
3,25	18,8 / 19	27	60	16	40	43	92	85	0,65
4,75	22	32	71,5	19	48	51	106	98,5	1,01
6,5	25	37	84,5	22	54	58	120	114	1,5
8,5	28	43,5	96,25	26,5	60	68,5	135	129,5	2,25
9,5	32	48	109	29	68	75	143	144	3,25
12	35	53	120,5	32	76	84	164	157	4,45
13,5	38	59	134	35	84	94	182	171	5,95
17	42	62	148,5	38	92	99	195	186	7,72
25	50	75	178	45	106	128	224	227	12,64
35	55	84	197,5	52	122	148	248	253	18,72
55	70	107	269,5	66	145	186	302	318	37
85	80	130	325	76	165	205	395	382	58

*Tolerance: +/- 5%

WARNING

- Failure to follow the regulations of this mounting instruction may cause serious consequences such as risk of injury.
- Read and understand these instructions before use.


1. General description:

POWERTEX Shackles are used as removable links to connect steel wire rope used in lifting operations and static systems, chain and other fittings. Screw pin shackles are used mainly for non-permanent applications. Safety bolt shackles are used for long-term or permanent applications or where the load may slide on the pin causing rotation of the pin.

Dee shackles are mainly used on one-leg systems whereas anchor- or bow shackles are mainly used on multi-leg systems.

2. Marking

Powertex shackles are generally marked with:

- Working Load Limit e.g. WLL 25t.
- Steel grade e.g. 6.
- Manufacturer's symbol e.g. Powertex, PTEX or PX.
- Traceability code e.g. F3 (indicating a particular batch).
- CE conformity code  + 

Additional Powertex shackles are marked with the following:

- size in inches e.g. 1 3/4.
- arrows to indicate 45 degree angle.
- according to EN 13889: EN (from 2t and up).



Powertex shackles meet all relevant requirements of the Machinery Directive 2006/42/EC and its latest amendments.

3. Finish

Powertex Shackles are hot dipped galvanized.

4. Certification

Powertex shackles are in compliance with:

EN 13889

AS 2741

US Federal Specification RR-C-271

Although EN 13889 only cover the range of Working Load Limits 0,5 t to 25 t maximum, the Powertex shackles are all manufactured according to EN 13889.

5. Testing

Powertex shackles are proofload tested at WLL x 2.

6. Instruction for use

Select the correct type and WLL of shackle and WLL for the particular application. If extreme circumstances or shock loading may occur, this must be well taken into account when selecting the correct shackle. Please note that commercial shackles are not to be used for lifting applications.

7. Assembly

Shackles should be inspected before use to ensure that (if criterias are not in place, the shackle must be rejected):

- the body and the pin of the shackle are both identifiable as being of the same size, type and mark;
- all markings are readable;
- the threads of the pin and the body are undamaged;
- the body and pin are not distorted;
- the body and pin are not unduly worn;
- the body and pin are free from nicks, gouges, cracks and corrosion.
- never use a safety bolt type shackle without using a secure pin.
- shackles may not be heat treated as this may affect their WLL.
- never modify, repair or reshape a shackle.

Ensure, where appropriate, that the pin is correctly screwed into the shackles eye, i.e. tighten finger tight, then lock using a small tommy bar

or suitable tool so that the collar of the pin is seated on the shackle eye. Ensure that the pin is of the correct length so that it penetrates the full depth of the screwed eye and allows the collar of the pin to bed on the surface of the drilled eye.

In all cases, when the pin is correctly fitted in the body of the shackle, the jaw width A should not be significantly reduced.

Incorrect seating of the pin may be due to a bent pin, the thread fitting too tightly or misalignment of pin holes. Do not use the shackle under these circumstances.

Never replace a shackle pin except with one of the same size type and mark as it may not be suitable for the loads imposed.

8. Usage

Select the correct type of shackle for a particular application from the information given in the below mentioned situations:

Shackles should not be used in a manner that imposes a side loading unless specifically permitted by the manufacturer. In general this means that the shackle body should take the load along the axis of its central line. (See figure A.1).




Fig. A.1

When using shackles in conjunction with multi-leg slings, due consideration should be given to the effect of the angle between the legs of the sling. As the angle increases so does the load in the sling leg and consequently in any shackle attached to the leg.

When a shackle is used to connect two slings to the hook of a lifting machine, it should be a bow type shackle assembled with the slings in the shackle body and the hook engaged with the shackle pin. The included angle between the slings should not exceed 120°.

To avoid eccentric loading of the shackle a loose spacer may be used on either end of the shackle pin (see figure A.2). Do not reduce the width between the shackle jaws by welding washer or spacers to the inside faces of the eyes or by closing the jaws, as this will have an adverse effect on the properties of the shackle.




Fig. A.2

When a shackle is used to secure the top block of a set of rope blocks the load on this shackle is increased by the value of the hoisting effect.

Avoid applications where due to movement (e.g. of the load or the rope) the shackle pin can roll and possibly unscrew. (See figures A.3 and A.4).




Fig. A.3

Correct: Shackle pin cannot turn

Incorrect: shackle pin bearing on running line can work loose




Fig. A.4

Correct - use two ropes with eyes




Fig. A.4

Incorrect - the load is unstable and if the load shifts the sling will unscrew the shackle pin.

In applications where the shackle is to be left in place for a prolonged period or where maximum pin security is required, use a bolt with hexagon head, hexagon nut and split cotter pin..

Avoid applications where the load is unstable (See figure A.4).

Shackles should not be modified, heat treated, galvanized or subject to any plating process without the approval of the manufacturer.

Do not use a shackle outside the temperature range of -20°C to +200°C without consulting the manufacturer.

Shackles should not be immersed in acidic solutions or exposed to acid fumes or other chemicals without the approval of the manufacturer.


Attention is drawn to the fact that certain production processes involve acidic solutions, fumes etc. and in these circumstances the manufacturer's advice should be sought.

The rating of shackles to EN 13889 assumes the absence of exceptionally hazardous conditions. Exceptionally hazardous conditions include offshore activities, the lifting of persons and lifting of potentially dangerous loads such as molten metals, corrosive materials or fissile materials. In such cases the degree of hazard should be assessed by a competent person and the safe working load reduced accordingly from the working load limit.

9. Side loads

Side loads should be avoided, as the products are not designed for this purpose. If side loads cannot be avoided, the WLL of the shackle must be reduced:

Load angle	Reduction for side loading New Working Load Limit
0°	100% of original WLL
45°	70% of original WLL
90°	50% of original WLL



In-line lifting is considered to be a load perpendicular to the pin and in the plane of the bow. The load angles in the table are the deviating angles from the in-line loads.

When using shackles in connection with multi-leg slings, due consideration should be given to the effect of the angle between the legs of the sling. As the angle increases, so does the load in the sling leg and consequently in any shackle attached to that leg.

End of use/Disposal

Powertex shackles shall always be sorted / scrapped as general steel scrap.

Main material is steel grade 6, and hot dip galvanized. Split is AISI 304. The supplier will assist you with the disposal, if required.

Must be inspected at least once a month and must undergo a complete overhaul at least every 12 months. Please note local rules and regulations must be complied with regards to inspection.

Disclaimer

We reserve the right to modify product design, materials, specifications or instructions without prior notice and without obligation to others.

If the product is modified in any way, or if it is combined with a non-compatible product/component, we take no responsibility for the consequences in regard to the safety of the product.

Declaration of conformity

SCM Citra OY

Asessorinkatu 3-7

20780 Kaarina

Finland

www.powertex-products.com

hereby declares that Powertex product as described above is in compliance with EC Machinery Directive 2006/42/EC.

UK Declaration of conformity

SCM Citra OY

Asessorinkatu 3-7


20780 Kaarina, Finland

www.powertex-products.com


hereby declares that the POWERTEX product as described above is in compliance with the Supply of Machinery (Safety) Regulations 2008.

POWERTEX Sjækler

Brugsanvisning (DK)




PDSB med sikkerhedsbolt




PDSP med skruestift

WLL ton	Stift Ø d1	a*	c*	d	d2	mm		Vægt PDSB kg	Vægt PDSP kg
						H1 PDSB	H1 PDSP		
0,33	6 / 6,3	10	21,85	5	14,5	33,5	29	0,027	0,025
0,5	8	13	22	6,5	17,5	42,5	38	0,05	0,042
0,75	9,5	13,5	25,5	8	21	47	42,5	0,086	0,068
1	11,2	17	30,9	10	25	56,5	51,5	0,160	0,130
1,5	12,7	18,5	36,4	11	27	63,5	58	0,215	0,185
2	15,8	20,6	41,4	12,7	30,5	75,5	67	0,340	0,29
3,25	18,8 / 19	27	51	16	40	92	85	0,6	0,58
4,75	22	32	63	19	48	106	98,5	1,02	0,93
6,5	25	37	72	22	54	120	114	1,6	1,45
8,5	28	43,5	81,75	26,5	60	135	129,5	2,3	2,06
9,5	32	48	94	29	68	143	144	3,33	2,91
12	35	53	102	32	76	164	157	4,15	4,15
13,5	38	59	113,5	35	84	182	171	5,87	5,5
17	42	62	123	38	92	195	186	7,6	6,97
25	50	75	148	45	106	224	227	11,7	11,22
35	55	84	174,5	52	122	248	253	17,84	16,36
55	70	107	205,5	66	145	302	318	33	31

*Tolerance: +/- 5%



PBSB med sikkerhedsbolt



PBSP med skruestift

WLL ton	Stift Ø d1	a*	c*	d	d2	e	mm		Vægt kg
							H1 PBSB	H1 PBSP	
0,33	6 / 6,3	10	22,6	5	14,5	15,5	33,5	29	0,026
0,5	8	13	29	6,5	17,5	20	42,5	38	0,048
0,75	9,5	13,5	31	8	21	21,5	47	42,5	0,082
1	11,2	17	36,5	10	25	26,2	56,5	51,5	0,150
1,5	12,7	18,5	42,9	11,3	27	29,5	63,5	58	0,20
2	15,8	20,6	47,75	12,7	30,5	33,3	75,5	67	0,30
3,25	18,8 / 19	27	60	16	40	43	92	85	0,65
4,75	22	32	71,5	19	48	51	106	98,5	1,01
6,5	25	37	84,5	22	54	58	120	114	1,5
8,5	28	43,5	96,25	26,5	60	68,5	135	129,5	2,25
9,5	32	48	109	29	68	75	143	144	3,25
12	35	53	120,5	32	76	84	164	157	4,45
13,5	38	59	134	35	84	94	182	171	5,95
17	42	62	148,5	38	92	99	195	186	7,72
25	50	75	178	45	106	128	224	227	12,64
35	55	84	197,5	52	122	148	248	253	18,72
55	70	107	269,5	66	145	186	302	318	37
85	80	130	325	76	165	205	395	382	58

*Tolerance: +/- 5%



ADVARSEL

- Manglende overholdelse af bestemmelserne i denne monteringsanvisning kan resultere i alvorlige konsekvenser såsom risiko for personskade.
- Læs og forstå disse anvisninger inden brug.

1. Generel beskrivelse:

POWERTEX Sjækler bruges som aftagelige led til at forbinde stålwireline, der anvendes i hejseaktiviteter og statiske systemer, kæde- og andre beslag. Skrustiftsjækler bruges hovedsageligt til ikke-permanente anvendelser. Sikkerhedsboltsjækler bruges til langvarige eller permanente anvendelser, eller hvor belastningen kan glide på stiftens, hvilket kan få stiftens til at rotere.

D-sjækler bruges hovedsageligt på systemer med ét ben, mens ankereller buesjækler hovedsageligt bruges på systemer med flere ben.

2. Mærkning

Powertex-sjækler er generelt mærket med:

- Driftsbelastningsgrænse, f.eks. WLL 25t.
- Stålkvalitet, f.eks. 6.
- Producentsymbol, f.eks. Powertex, PTEX eller PX.
- Sporbarhedskode, f.eks. F3 (som angiver en bestemt batch).
- CE-overensstemmelseskode **CE + UK**

Yderligere Powertex-sjækler er mærket med følgende:

- størrelse i tommer, f.eks. 1 3/4.
- pile til at angive 45 graders vinkel.
- i overensstemmelse med EN 13889: EN (fra 2t og op).

hævet pude (bagpå) til individuel stempling



Powertex-sjækler opfylder alle relevante krav i Maskindirektiv 2006/42/EF og dets seneste ændringer.

3. Overfladebehandling

Powertex-sjækler er varmegalvaniserede.

4. Certificering

Powertex-sjækler er i overensstemmelse med:

EN 13889

AS 2741

US Federal Specification RR-C-271

Selvom EN 13889 kun dækker intervallet af grænser for driftsbelastning 0,5 til 25t maksimum, er alle Powertex-sjækler fremstillet i overensstemmelse med EN 13889.

5. Afprøvning

Powertex-sjækler er blevet testet med en prøvebelastning på WLL x 2.

6. Brugsanvisning

Vælg den korrekte type sjækkel, og WLL for sjæklen og WLL for den bestemte anvendelse. Hvis der kan opstå ekstreme forhold eller slagbelastning, skal der tages hensyn til dette, når den korrekte sjækkel vælges. Bemærk, at kommercielle sjækler ikke må bruges til hejseformål.

7. Montering

Sjækler bør inspiceres inden brug (hvis kriterier ikke opfylles, skal sjæklen afvises) for at sørge for, at:

- både sjæklets hoveddel og stift kan identificeres som værende af samme størrelse, type og samme mærke;
- alle mærkninger kan læses;
- gevindene på stiftens og hoveddelen er ubeskadigede;
- hoveddelen og stiftens ikke er forvrængede;
- hoveddelen og stiftens ikke er overdrevet slidte;
- hoveddelen og stiftens er fri for hak, udhullinger, revner og korrosion.
- brug aldrig en sjækkel af sikkerhedsboltypen uden brug af en sikkerhedsstift.
- sjækler må ikke varmebehandles, da dette kan påvirke deres WLL.
- du må aldrig modificere, reparere eller omforme en sjækkel.

Hvor det er relevant, bør du sørge for, at stiftens er skruet korrekt ind i sjækkeløjet, dvs. spænd fingerstramt, og lås derefter med en lille momentstang eller et egnert værktøj, så stiftens krave indsættes i

sjækkeløjet. Sørg for, at stiften har den rette længde, så den trænger helt ind i skrueøjet og lader stiftens krave blive indsat på overfladen af det borede øje.

Under alle omstændigheder bør kæbebredden A ikke være betydeligt reduceret, når stiftens er monteret korrekt i sjæklets hoveddel.

Forkert indsætning af stiftens kan forårsages af en bøjet stift, en for stram gevindmontering er for stram eller skævhed i stifthuller. Brug ikke sjæklen under disse omstændigheder.

Sjæklestiftens må aldrig udskiftes, undtagen med en stift af samme størrelsesstype og samme mærke, da den muligvis ikke er velegnet til de pålagte belastninger.

8. Anvendelse

Vælg den rette type sjækkel til en bestemt anvendelse fra oplysningerne angivet i nedenstående situationer:

Sjækler bør ikke bruges på en måde, der pålægger en sidebelastning, med mindre det tillades specifikt af producenten. Generelt betyder dette, at sjækelhoveddelen bør tage belastningen langs dens midterlinjes akse. (Se figur A.1.)




Fig. A.1

Når der bruges sjækler sammen med seler med flere ben, bør der tages passende hensyn til virkningen af vinklen mellem selens ben. Når vinklen øges, stiger belastningen i selebenet og dermed i enhver sjækkel fastgjort til benet.

Når en sjækkel bruges til at forbinde to seler til krogen af en hejsemaskine, bør den være en buesjækkel monteret med selerne i sjækelhoveddelen og krogen koblet til sjækelstiften. Den inkluderede vinkel mellem selerne bør ikke overstige 120°.

For at undgå asymmetrisk belastning af sjæklen kan der bruges et løst afstandsstykke på hver ende af sjækelstiften (se figur A.2). Reducer ikke afstanden mellem sjækelkæberne ved brug af svejseskive eller afstandsstykke til indersiden af øerne eller ved at lukke kæberne, da dette vil have en negativ indvirkning på sjæklets egenskaber.






Fig. A.2

Når en sjækkel anvendes til at sikre den øverste blok af et sæt rebblokke, øges belastningen på denne sjækkel med værdien af løftevirkningen.


Undgå anvendelser, hvor sjækelstiften pga. bevægelse (f.eks. af belastningen eller rebet) kan rulle og muligvis løsne sig. (Se figur A.3 og A.4.)


Fig. A.3

Korrekt: Sjæklestift kan ikke dreje

 Forkert: sjæklestiftleje på løbelinje
kan løsne sig

Fig. A.4

Korrekt - brug to reb med øjer


Fig. A.4

 Forkert - belastningen er ustabil, og hvis belastningen skifter, løsner
selen sjæklestiften.

I anvendelser, hvor sjæklen skal sidde på plads gennem en længere periode, eller hvor der kræves maksimal stiftsikkerhed, kan du bruge en bolt med sekskantet hoved, en sekskantet møtrik eller splitstift.

Undgå anvendelser, hvor belastningen er ustabil (se figur A.4).

Sjækler bør ikke modificeres, varmebehandles, galvaniseres eller udsættes for nogen form for galvaniseringsproces uden godkendelse fra producenten.

Brug ikke en sjækkel uden for temperaturintervallet på -20°C til +200°C uden at kontakte producenten.


Sjækler bør ikke nedslænkes i syreopløsninger eller udsættes for syredampe eller andre kemikalier uden godkendelse af producenten. Der gøres opmærksom på, at da visse produktionsprocesser involverer syreopløsninger, dampning osv., bør producenten spørges til råds under disse omstændigheder.

Vurderingen af sjækler til EN 13889 antager fraværet af særligt farlige forhold. Særligt farlige forhold omfatter offshore-aktiviteter, løftning af personer og løftning af potentielt farlige belastninger såsom smelte metal, korrosive materialer eller fissile materialer. I sådanne tilfælde bør faregraden vurderes af en kompetent person, og den sikre driftsbelastning bør reduceres fra driftsbelastningsgrænsen i overensstemmelse hermed.

9. Sidebelastninger

Sidebelastninger bør undgås, da produktet ikke er beregnet til dette formål. Hvis sidebelastninger ikke kan undgås, skal sjæklenes WLL reduceres:

Belastningsvinkel	Reduktion for sidebelastning Ny arbejdsværdigrænse (WLL)
0°	100% af den originale WLL
45°	70% af den originale WLL
90°	50% af den originale WLL



Løft på linje anses for at være en belastning vinkelret med stiften og på buens niveau. Belastningsvinklerne på tabellen er de afvigende vinkler fra linjebelastningerne.

Når der bruges sjækler i forbindelse med seler med flere ben, bør der tages passende hensyn til virkningen af vinklen mellem selens ben. Når vinklen øges, stiger belastningen i selebenet og dermed i enhver sjækkel fastgjort til dette ben.

Slut på anvendelse/Bortskaffelse

Powertex-sjækler skal altid sorteres/kasseres som generelt stålskrot. Hovedmaterialet er stålkvalitet 6, og det er varmegalvaniseret. Split er AISI 304.

Vi vil være dig behjælpelig med bortskaffelse, hvis det kræves.

Skal eftersettes mindst en gang om måneden, og skal gennemgå et hovedeftersyn mindst hver 12. måned. Bemærk venligst lokale regler og regulative skal overholdes med hensyn til inspektion.

Ansvarsfraskrivelse

Vi forbeholder os retten til at modifcere produktdesign, materialer, specifikationer eller anvisninger uden forudgående varsel og uden forpligtelse over for andre.

Hvis produktet modifcieres på nogen måde, eller hvis det kombineres med et ikke-kompatibelt produkt/komponent, påtager vi os intet ansvar for konsekvenserne hvad angår produktets sikkerhed.

Overensstemmelseserklæring
SCM Citra OY
Asessorinkatu 3-7
20780 Kaarina
Finland
www.powertex-products.com

erklærer hermed, at Powertex produktet, som beskrevet herover, er i overensstemmelse med EF-maskindirektiv 2006/42/EF og senere ændringer.

CertMax+

The CertMax+ system is a unique leading edge certification management system which is ideal for managing a single asset or large equipment portfolio across multiple sites. Designed by the Lifting Solutions Group, to deliver optimum asset integrity, quality assurance and traceability, the system also improves safety and risk management levels.




User Manuals

You can always find the valid and updated User Manuals on the web.
The manual is updated continuously and valid only in the latest version.

NB! The English version is the Original instruction.

The manual is available as a download under the following link:
www.powertex-products.com/manuals



POWERTEX



www.powertex-products.com