

GB Instruction for use
DK Brugsanvisning

POWERTEX



Short Link Lifting Chain PSL Grade 8

User Manual



POWERTEX Short Link Lifting Chain PSL Grade 8

Instruction for use (GB) (Original instructions)

General:


POWERTEX PSL Grade 8 chains are intended to be cut in suitable lengths by professional sling shops and used as parts making up assembled lifting equipment such as chain slings or lifting beams. The assembled lifting equipment must not be put into service until the complete lifting assembly has been certified to be in accordance to the Machinery directive 2006/42/EC. Make sure to follow the chain sling or lifting equipment manufacturer's instructions. PSL short link lifting chains are CE-marked and delivered with a POWERTEX Certificate & Declaration of Conformity in accordance to the Machinery Directive 2006/42/EC. The chains follow also EN 818-2 Grade 8.

Standard applied: EN 818-2 and AS2321.

Proof load testing: Each link has been proof load tested 2,5 x WLL at the factory prior delivery.

Temperature range: -40°C up to +400°C (200-400°C requires reduction of WLL).

Safety factor: 4:1.



Data and dimensions

Model	Chain Ø d (mm)	EN818-2 WLL (ton)	AS2321 WLL (ton)	LC (kN)	Proof load (kN)	Min breaking force (kN)	Pitch p (mm)	W1 min (mm)	W2 max. (mm)	Weight (kg/m)
PSL-6-8	6	1,12	1,1	22,4	28,3	45,2	18	7,8	22,2	0,8
PSL-8-8	8	2	2	40	50,3	80,4	24	10,4	29,6	1,5
PSL-10-8	10	3,15	3,2	63	78,5	126	30	13,0	37,0	2,3
PSL-13-8	13	5,3	5,3	100	133	212	39	16,9	48,1	3,9
PSL-16-8	16	8	8	160	201	322	48	20,8	59,2	5,8
PSL-20-8	20	12,5	12,5	250	314	503	60	26,0	74,0	8,9

Use in adverse environments

Temperature's effect on working load limit (WLL)

Account should be taken to the temperature that can be reached by the chain in service. PSL chain Grade 8 can be used in temperatures between -40°C and up to +200°C without reduction of the working load limits.

Elevated usage temperatures would result in a reduction of WLL:

200-300°C -10% reduction of WLL

300-400°C -25% reduction of WLL

If the chain sling reaches temperatures that exceed the allowed temperatures the chains should be discarded or be returned to your distributor for evaluation.

Corrosive/Acidic conditions

Grade 8 is not suitable for use in corrosive environments. Chains in grade 8 should not be used either immersed in acidic solutions or exposed to acid fumes. The chains should for the same reason not be hot dip galvanized or exposed to electrolytic finishing without permission from the manufacturer.

Chemical affects

Consult with your distributor in case the chains are to be exposed to chemicals especially combined with high temperatures.

Hazardous conditions

In particularly hazardous conditions including offshore activities, lifting of a person, and lifting of potentially dangerous loads such as molten metals, corrosive materials or fissile materials, the degree of hazard should be assessed by a competent person and the working load limit adjusted accordingly.

Ensure before first use




- a) the chain is precisely as ordered;
- b) the manufacturer's Certificate/Declaration of Conformity and User manual is available;
- c) the identification and working load limit marking on the chain/ chain packing correspond to the information on the certificate;
- d) full details of the chain is recorded in a register;

Before each use of lifting chains

Make sure to follow the chain sling or lifting equipment manufacturer's user instructions. The chain should be inspected for obvious damage or deterioration. If faults are found during this inspection, the procedure given in "Inspections and maintenance" should be followed. Chains must always be used without twists or knots. Shortening hooks may be used to adjust chain legs that needs shortening.

Reduction of WLL due to sharp edges

It is important to protect the chain links from damages from sharp edges. If proper padding can't be used the WLL of the sling needs to be reduced according to below reduction table

Edge load	R = larger than 2 x chain Ø	R = larger than chain Ø	R = chain Ø or smaller
			
Load factor	1 x WLL	0,7 x WLL	0,5 x WLL

Storage


Store chains in a dry and clean area well protected from corrosion.

Inspections and maintenance

Daily inspection

During service, chains are subjected to conditions that may affect their safety. It is necessary, therefore, to ensure, as far as it is reasonably practicable, that the chain is safe for continued use. If any of below damages are found the chain should be taken out of service for a thorough examination:


- a) The chain has been overloaded. If the chain slings have extended or if free rotation between the links are missing or if there is a noticeable difference in length between legs in a multi-leg sling, the reason can be that the chain has been overloaded.
- b) Wear by contact with other objects usually occurs on the outside of the straight portions of the links where it is easily seen and measured. Wear between adjoining links is hidden. The chain should be slack and adjoining links rotated to expose the inner end of each link. Inter-link wear (in the bearing points) is tolerated until the mean value of two measured values 90° against each other has been reduced to 90% of the nominal diameter
- c) Cuts, nicks, gouges, cracks, excessive corrosion, heat discoloration, bent or distorted links or any other defects.



Thorough examination

A thorough examination should be carried out of a competent person at intervals not exceeding twelve months. This interval should be less where deemed necessary in the light of service conditions. Records of such examinations should be maintained. Chains should be thoroughly cleaned to be free from oil, dirt and rust prior to examination. Any cleaning method which does not damage the parent metal is acceptable. Methods to avoid are those using acids, overheating, removal of metal or movement of metal which may cover cracks or surface defects. Adequate lighting should be provided and the chain should be examined throughout its length to detect any evidence of overloading, wear, distortion, cracks or external damages that may affect safety.

Repair: If any chain link within the leg of a chain sling is required to be replaced then the entire length of the chain leg need to be renewed.

 **End of use/Disposal**

Chains shall always be sorted/scrapped as general steel scrap. Your POWERTEX distributor will assist you with the disposal, if required.

EC Declaration of Conformity

SCM Citra OY
 Asessorinkatu 3-7
 20780 Kaarina Finland
 www.powertex-products.com

hereby declares that the POWERTEX product as described above is in compliance with EC Machinery Directive 2006/42/EC and EN 818-2.

UK Declaration of conformity

SCM Citra OY
 Asessorinkatu 3-7
 20780 Kaarina, Finland
 www.powertex-products.com

hereby declares that the POWERTEX product as described above is in compliance with the Supply of Machinery (Safety) Regulations 2008 & BS EN 818-2.

POWERTEX Kortleddet kæde PSL klasse 8

Brugsanvisning (DK)

Generelt:


POWERTEX PSL klasse 8 kæde er beregnet til at blive skåret i passende længder af professionelle kædeslinsproducenter og brugt som dele, der udgør samlet løfteudstyr såsom kædeslins eller løfteåg. Det samlede løfteudstyr må ikke tages i brug, før hele løfteenheden er certifice-ret til at være i overensstemmelse med maskindirektivet 2006/42/EC. Sørg for at følge kædeslingets eller løfteanordningens anvisninger. PSL kortleddede løftkæder er CE-mærkede og leveres med et POWERTEX-certifikat og overensstemmelseserklæring i henhold til maskindirektivet 2006/42/EC. Kæderne overholder også EN 818-2 (klasse 8)

Standard: EN 818-2 og AS2321

Prøvebelastning: Hvert led er blevet prøvebelastet med 2,5 x WLL på fabrikken før levering

Arbejdstemperatur: -40°C op til +200°C (200-400°C kræver reduktion af WLL).

Sikkerhedsfaktor: 4:1



Data og dimensioner

Model	Kæde Ø d (mm)	EN818-2 WLL (ton)	AS2321 WLL (ton)	LC (kN)	Prøvebelastning (kN)	Min. brudstyrke (kN)	Pitch p (mm)	W1 min (mm)	W2 maks. (mm)	Vægt (kg/m)
PSL-6-8	6	1,12	1,1	22,4	28,3	45,2	18	7,8	22,2	0,8
PSL-8-8	8	2	2	40	50,3	80,4	24	10,4	29,6	1,5
PSL-10-8	10	3,15	3,2	63	78,5	126	30	13,0	37,0	2,3
PSL-13-8	13	5,3	5,3	100	133	212	39	16,9	48,1	3,9
PSL-16-8	16	8	8	160	201	322	48	20,8	59,2	5,8
PSL-20-8	20	12,5	12,5	250	314	503	60	26,0	74,0	8,9

Brug i ugunstige miljøer

Temperaturers indvirkning på WLL

Der skal tages hensyn til den temperatur, der kan opnås når kæden er i drift. PSL kæde i klasse 8 kan bruges i temperaturer mellem -40°C og op til +200°C uden reduktion af WLL.

Forhøjede brugstemperaturer vil resultere i en reduktion af WLL:

200-300°C -10% reduktion af WLL

300-400°C -25% reduktion af WLL

Hvis kædeslinget når temperaturer, der overstiger de tilladte temperaturer, skal kæderne kasseres eller returneres til din forhandler til evaluering.

Ætsende/sure forhold

Klasse 8 er ikke egnet til brug i korrosive miljøer. Kæder i klasse 8 bør hverken anvendes nedsænket i sure opløsninger eller blive udsat for sure dampe. Kæderne bør af samme grund ikke varmgalvaniseres eller udsættes for elektrolytisk efterbehandling uden tilladelse fra producenten.

Kemisk påvirkning

Rådfør dig med din forhandler i tilfælde af, at kæderne skal udsættes for kemikalier, især hvis kombineret med høje temperaturer.

Farlige forhold

Under særligt farlige forhold, herunder offshoreaktiviteter, løft af en person og løft af potentielt farlige byrder såsom smeltede metaller, ætsende materialer eller fissile materialer, bør graden af fare vurderes af en kompetent person, og belastningsgrænsen justeres i overensstemmelse hermed.

Før første anvendelse

Sikr dig at




- kæden er præcis som bestilt;
- producentens certifikat/overensstemmelseserklæring og brugervejledning er tilgængelig;
- identifikations- og belastningsmærkningen på kæden/kædepakningen svarer til oplysningerne på certifikatet;
- alle detaljer om kæden er registreret i et register;

Før første brug af løftkæder

Sørg for at følge kædeslingets eller løfteudstørsproducentens brugervejledning. Kæden bør inspiceres for åbenlyse skader eller forringelse. Hvis der konstateres fejl under denne inspektion, skal proceduren i "Eftersyn og vedligeholdelse" følges. Kæder skal altid bruges uden snoninger eller knuder. Opkorterkrøge kan bruges til at justere længden på kædeparter, som ønskes opkortet.

Reduktion af WLL grundet skarpe kanter

Det er vigtigt at beskytte kædeleddene mod skader fra skarpe kanter. Hvis korrekt polstring ikke kan bruges, skal slingets WLL reduceres i henhold til nedenstående reduktionstabel:

Hjørne last	R = større end 2 x kæde Ø	R = større end kæde Ø	R = mindre end kæde Ø
			
Last faktor	1 x WLL	0,7 x WLL	0,5 x WLL

Opbevaring


Opbevar kæder i et tørt og rent område, godt beskyttet mod korrosion.

Eftersyn og vedligeholdelse

Daglig inspektion

Under brug er kæder udsat for forhold, der kan påvirke deres sikkerhed. Det er derfor nødvendigt at sikre, så vidt det er praktisk muligt, at kæden er sikker til fortsat brug. Hvis der konstateres nogen af nedenstående skader, skal kæden tages ud af drift for en grundig undersøgelse:

- a) Kæden har været overbelastet. Hvis kædeslinget er trukket ud, eller hvis fri rotation mellem leddene mangler, eller hvis der er en mærkbar forskel i længden mellem parterne i et fler-parts sling, kan årsagen være, at kæden er blevet overbelastet.
- b) Slid ved kontakt med andre emner forekommer normalt på ydersiden af de lige dele af leddene, hvor det let kan ses og måles. Slid mellem tilstødende led er skjult. Kæden skal være slap og tilstødende led drejes for at blotlægge den indvendige del af hvert led. Slid mellem led (i lejepunkterne) tolereres, indtil middelværdien af to målte værdier 90° mod hinanden er reduceret til 90% af den nominelle diameter.
- c) Tjek for snit, hakker, huller, revner, overdreven korrosion, varmemisfarvning, bøje eller forvrængede led eller andre defekter.



Grundig undersøgelse

Der bør foretages en grundig undersøgelse af en kompetent person, med intervaller på højst tolv måneder. Dette interval bør være mindre, hvor det skønnes nødvendigt i lyset af arbejdsforholdene. Optegnelser over sådanne undersøgelser bør opbevares. Kæder bør rengøres grundigt for at være fri for olie, snavs og rust før undersøgelse. Enhver rengøringsmetode, der ikke beskadiger grundmetallet, er acceptabel. Metoder, der skal undgås, er dem, der bruger syrer, overophedning, fjernelse af metal eller bevægelse af metal, som kan dække revner eller overfladefejl. Der skal sørges for tilstrækkelig belysning, og kæden bør undersøges i hele dens længde for at opdage tegn på overbelastning, slid, forvrængning af revner eller eksterne skader, der kan påvirke sikkerheden.

Reparation: Hvis et led i kædeparten eller kædeslinget skal udskiftes skal hele kædelængden af kædeparten fornyes.

Skrotning/Bortskaffelse



Kæder skal altid sorteres/bortskaffes som almindeligt stålskrot. Din POWERTEX-distributør hjælper dig med bortskaffelse, hvis det kræves.

Overensstemmelseserklæring

SCM Citra OY
 Asessorinkatu 3-7
 20780 Kaarina Finland
 www.powertex-products.com

erklærer hermed, at POWERTEX-produktet som beskrevet ovenfor er i overensstemmelse med EC Maskindirektivet 2006/42/EC og EN 818-2 (WLL+25%).

UK Declaration of conformity

SCM Citra OY
 Asessorinkatu 3-7
 20780 Kaarina, Finland
 www.powertex-products.com

erklærer hermed, at POWERTEX produktet som beskrevet ovenfor er i overensstemmelse med Machinery (Safety) Regulations 2008 & BS EN 818-2.

CertMax+

The CertMax+ system is a unique leading edge certification management system which is ideal for managing a single asset or large equipment portfolio across multiple sites. Designed by the Lifting Solutions Group, to deliver optimum asset integrity, quality assurance and traceability, the system also improves safety and risk management levels.

CertMax

Marking

The POWERTEX PSL Chain links are marked with factory symbol, Grade and traceability code marking of the batch.

The POWERTEX Short Link Chain is **CE** and **UKCA** marked.

Standard: EN818-2 and AS2321.



User Manuals

You can always find the valid and updated User Manuals on the web. The manual is updated continuously and valid only in the latest version.

NB! The English version is the Original instruction.

The manual is available as a download under the following link:
www.powertex-products.com/manuals



Product compliance and conformity

SCM Citra OY
Asessorinkatu 3-7
20780 Kaarina Finland
Finland
www.powertex-products.com



POWERTEX

www.powertex-products.com